

FIELD SERVICE / HYDRAULICS

PARKER HYDRAULIC PUMP FIELD SERVICE REPORT

INSPECTION / PRESERVATION / PACKING & TAGGING

Model PV063R9K1T1NMFCK0424 / Serial SN-SAMPLE-01

CEMENT PLANT CLIENT / MAINTENANCE

Completion Date / 14 October

ISO 9001:2015 · ISO 14001 CERTIFIED · ISO 45001 CERTIFIED

PMS / TECHNICAL SERVICES

RECEIPT & IDENTIFICATION RECORD

PROJECT / SITE

CEMENT PLANT

Department: Maintenance
Date of visit: 9th of September
Received by: PMS Engineer
Delivery note: N/A
PO number: N/A

ITEM DESCRIPTION

HYDRAULIC PUMP

Service state: Used
Quantity: One pump
Condition: Used, weathered; requires evaluation

NAMEPLATE

Parker Hannifin / PMDE — Chemnitz
Germany

IDENTIFICATION

Model / Type: PV063R9K1T1NMFCK0424
Serial number: SN-SAMPLE-01
Series / Code: 4545 / LM




RECEIVED CONDITION



PUMP BODY


CLEANING AND EXTERNAL COATING
















PRESERVATION














PACKING AND TAGGING







PACKING LIST

Accepted

Packing List No: PMS-PL-PV063-261014-058

Customer: Tasluja Ciment Factory

Box Number: PV064-BX-01

Box Dimensions (L x W x H) :600mm x 400mm x 400mm

Cross Weight: 75 Kg **Net Weight:** 60 Kg

Preservation Expiration Date: 14 Of April 2027

Item No.	Part Code	Quantity	Description	Remarks
001	PMS-PV063-CB2S2G-01	1	Hydraulic Pump	

VIEW 03







RECOMMENDATIONS

IMMEDIATE ACTION

01

Replace the compensator and regulator assembly

NEXT MAINTENANCE INTERVAL

01 BEARINGS

02 VALVE PLATE

Replace these components during the next planned maintenance interval.

QUALITY THAT SPEAKS

FIELD SERVICE / HYDRAULICS / TECHNICAL SERVICES



CONTACT PMS

contact@promachinistsolutions.com

www.promachinistsolutions.com

07733683399 • 07733683300

ISO 9001:2015 · ISO 14001 CERTIFIED · ISO 45001 CERTIFIED

© 2026 PMS. All rights reserved.